TE-PUFPLUS Hi-Vol One-Point Flow Check Data Form
Site Information
Full Site Name: Portage - Hwy 12
Site Abbreviation: PTG Sampler Serial No.: 1001
Field Technician Name: Katil Healy & Kate Haile Date: 8/12/21 Time: 13:23 CST
Site Conditions & Sensor Checks *allow Temperature/Pressure standard to acclimate for 10 minutes before reading
Temp/Pressure Standard Make/Model: Deltacal DC 1
Temp/Pressure Standard Serial No.: 179112 Temp/Pressure Standard Certification Date: 2/2/21
Tamb transfer standard (°C) 25.6 Tamb PUFPLUS (°C) 26.1 (Tamb transfer standard - Tamb PUFPLUS) = °C
Is the PUFPLUS Temperature sensor within ±2°C of the Transfer Standard? (YES) NO (circle one)
Pamb transfer standard (mmHg) 743.5 Pamb PUFPLUS (mmHg) 743 (Pamb transfer standard - Pamb PUFPLUS) = 0.5 mmHg
Is the PUFPLUS Pressure sensor within ±10mmHg of the Transfer Standard? (YES) NO (circle one)
If both of the above are YES, sensor check is complete. Proceed with flow check.
• If either of the both is NO, use the TE-PUFPLUS Operator's Manual to troubleshoot and retry the sensor check. If the issue persists, add a calibration point to the faulty sensor as described in the SOP in Section 10.2.3. Note that a calibration was done here:
a cambration point to the faulty sensor as described in the sor in section 10.2.3. Note that a cambration was done here.
Orifice Make/Model: Graseby / TISCh Orifice Serial No.: 62 K
Orifice Slope "morifice": 10.46067 Orifice Intercept "borifice": -0.16706
Orifice Certification Date: 2/4/2/ *if using a "U" tube manometer, write "U-tube" in Make/Model and leave the other spaces blank
Manometer Make/Model: DWYEV 475 Mar FIII Manometer Serial No.: 00 7947
Manometer Certification Date: 2/4/21
One-Point Flow Check Procedure
*flow check is to be performed after the 5 th scheduled sample run of each month
1. Set up the sampler as if performing a flow calibration with certified orifice and manometer. No sample media
should be inside the module. Attach the orifice tubing to the manometer instead of the AutoCal sensor.
2. Turn on the hi-vol's motor at 0.225 m ³ /min for 10-15 minutes:
a. In the PUFPLUS Interface select "F3" for "Setup", navigate to "Diagnostics" and select "Ent", navigate to "MTR Control" and
select "Ent", navigate to "Qsys" and select "Ent", navigate to "MTR Setpoint" and select "Ent", enter 225 (units are liters/min) as the setpoint and select "Ent".
3. Record the Manometer Pressure.
P _{Manometer} (inH ₂ O)
4. Calculate the Manometer flow rate using the following equation:
$Q_{Manometer}\left(\frac{m^3}{\min}\right) = \frac{1}{m_{orifice}} * \left(\sqrt{P_{Manometer} * \left(\frac{P_{amb} * 298K}{760mmHg * T_{amb}}\right)} - b_{orifice}\right) = \frac{0.2314}{100mmHg * T_{amb}}$
* T_{amb} should be in degrees Kelvin: T_{amb} (°C) + 273 = T_{amb} (K)
5. Calculate the percent difference between 0.225 m³/min and Q _{Manometer} :
Percent Difference = $100*(1 - (Q_{Manometer} \div 0.225)) = 2.83$ %
6. Is the Percent Difference ≤±10%? (YES) NO (circle one)
a. If YES, flow check is complete.b. If NO, use the TE-PUFPLUS Operator's Manual to troubleshoot and retry the flow check. If the issue persists, the sampler will

need to be recalibrated. Contact the Project Leads.